



Intel® Dynamic Tuning Technology (Intel® DTT), Client Version 9.0

*9.0.11101.30293 Win 11 22H2 20H2, 20H1
ADL-P*

Release Notes

November 2022



INFORMATION IN THIS DOCUMENT IS PROVIDED IN CONNECTION WITH INTEL PRODUCTS. NO LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY THIS DOCUMENT. EXCEPT AS PROVIDED IN INTEL'S TERMS AND CONDITIONS OF SALE FOR SUCH PRODUCTS, INTEL ASSUMES NO LIABILITY WHATSOEVER AND INTEL DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY, RELATING TO SALE AND/OR USE OF INTEL PRODUCTS INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT.

A "Mission Critical Application" is any application in which failure of the Intel Product could result, directly or indirectly, in personal injury or death. SHOULD YOU PURCHASE OR USE INTEL'S PRODUCTS FOR ANY SUCH MISSION CRITICAL APPLICATION, YOU SHALL INDEMNIFY AND HOLD INTEL AND ITS SUBSIDIARIES, SUBCONTRACTORS AND AFFILIATES, AND THE DIRECTORS, OFFICERS, AND EMPLOYEES OF EACH, HARMLESS AGAINST ALL CLAIMS COSTS, DAMAGES, AND EXPENSES AND REASONABLE ATTORNEYS' FEES ARISING OUT OF, DIRECTLY OR INDIRECTLY, ANY CLAIM OF PRODUCT LIABILITY, PERSONAL INJURY, OR DEATH ARISING IN ANY WAY OUT OF SUCH MISSION CRITICAL APPLICATION, WHETHER OR NOT INTEL OR ITS SUBCONTRACTOR WAS NEGLIGENT IN THE DESIGN, MANUFACTURE, OR WARNING OF THE INTEL PRODUCT OR ANY OF ITS PARTS.

Intel may make changes to specifications and product descriptions at any time, without notice. Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined". Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them. The information here is subject to change without notice. Do not finalize a design with this information.

The products described in this document may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Intel, Dynamic Platform and Thermal Framework and the Intel logo are trademarks of Intel Corporation or its subsidiaries in the U.S. and other countries.

*Other names and brands may be claimed as the property of others. Copyright ©

2022 Intel Corporation. All rights reserved.

Contents

1	Introduction	5
1.1	Supported Operating Systems	5
1.2	Supported Hardware	5
1.3	Supported BIOS	5
1.4	Supported KSC.....	5
1.5	Supported Intel® Graphics Driver	5
1.6	Supported Collaterals.....	6
2	Installation and Configuration Guide.....	7
2.1	Intel® DTT 9.x Software Stack Installation Guide.....	7
2.1.1	BIOS Setup Guide.....	7
2.1.2	Intel® DTT Software Stack Installation	8
2.1.3	Driver Behavioral Considerations	8
2.2	Intel® DTT 9.x Configuration Tool Configuration Guide	8
2.2.1	Configuring Startup Scripts in DTT 9.x.....	8
2.2.2	Configuration Tool Quick Start Guide.....	9
2.2.3	Troubleshooting	9
3	Tools Support	11
4	Feature Set – New to this release	12
5	Issues – Fixed in this Release	13
6	Issues – Known in this Release.....	14

Tables

Table 1. Tool Support	11
Table 2. Fixed Issues	13
Table 3. Known Issues	14



Revision History

Package Definition	Intel® Dynamic Tuning Technology Software Package Revision	Release Date
ADL-P	9.0.11101.30293	November, 2022

Note: Intel® DTT 9.x version represents the DTT Client 9.x package version.

Intended Audience

The target audiences for the release notes are OEM/ODM platform thermal and hardware engineers, BIOS and system software engineers, component ingredient (WiFi PSM, WWAN, NVMe Storage, Camera) procurement and design engineers.

Where to Find the Release

This release can be found on the Validation Internet Portal (VIP):
<https://platformsw.intel.com> .

Customer Support

For OEM/ODM technical support, contact your assigned Intel enabling engineers.

1 *Introduction*

1.1 Supported Operating Systems

This package supports following Operating Systems.

- Microsoft Windows* 10 x64 Edition 22H2, 20H2, 20H1

Note: This is the information for validated platforms at ingredient level. For a complete list of supported hardware and operating systems, please refer to platform BKC or contact your Intel representative.

1.2 Supported Hardware

- ADL-P

Note: This version of Intel® DTT only supports Intel Mobile Platforms. This is the information for validated platforms. For a complete list of supported hardware and operating systems, please contact your Intel representative.

1.3 Supported BIOS

Please refer to the BKC to get the latest version.

1.4 Supported KSC

Please refer to the BKC to get the latest version.

1.5 Supported Intel® Graphics Driver

Please refer to the BKC to get the latest version.

Intel® DTT 9.0.11101.30293 Win 11 22H, 20H2, 20H1 Release Notes
November 2022

1.6 Supported Collaterals

Please refer to the below mentioned supporting documents for the latest update on DTT.

- Intel® Dynamic Tuning Technology 8.x BIOS Specification#613332
- 2020 Intel® Dynamic Tuning Technology Configuration Guide#618762
- Intel® Dynamic Tuning Technology Feature Enabling Guide#572349
- Intel® Dynamic Tuning Decommissioning IA-P/T State GFX P State Control Technical Advisory WW13, 2019#610760
- Intel® Dynamic Tuning Radio Frequency Interference Mitigation (RFIM) Policy Enabling and Validation White Paper#613280

2 *Installation and Configuration Guide*

2.1 Intel® DTT 9.x Software Stack Installation Guide

2.1.1 BIOS Setup Guide

Please make sure DTT is enabled in your BIOS setup menu.

- 1) Reboot the system and enter BIOS setup screen.
- 2) Go to "Intel Advanced Menu".
- 3) Enter "Power & Performance", then "CPU – Power Management Control" page.
 - a. Make sure "Intel(R) SpeedStep(tm)" is enabled.
 - b. Make sure "Turbo Mode" is enabled.
- 4) Enter "Thermal Configuration ", then "Intel(R) Dynamic Tuning Technology Configuration" page.
 - a. Ensure "Intel® Dynamic Tuning Technology" show as "Enabled".
 - b. Most everything will be pre-configured, so change settings as desired.
- 5) Save and Exit.

2.1.2 Intel® DTT Software Stack Installation

1. Install the Chipset and Graphic driver.
2. Install IPF infs. Once Installation is complete it will show under “System Devices” of Device Manager.
3. Install DTT infs. It will show under software components
4. Install tool/IpfdttUi_9.x_Install.exe
5. Reboot your system.
6. Make sure no device yellow bang in device manager.
7. Open <http://localhost:8888> in HTML5 web browser and press “Ctrl+F5” to reload.

Note: -

- For DTT use DTT UI and for development of tools using IPF use IPF UI.
- UI is only for tuning purpose, no need to install on end-user system.
-

2.1.3 Driver Behavioral Considerations

- Windows service Wudfpf.sys is not loaded in the beginning sometimes might cause DTT device INT3400 unable to be loaded at the first time. Windows will try to load the driver again once Wudfpf.sys is loaded. There will be a warning event (ID: 219) found in event viewer, WUDFRd failed to load DTT device. If the driver is installed successfully, the message could be ignored.

2.2 Intel® DTT 9.x Configuration Tool Configuration Guide

For OEMs testing, validation, and system performance optimization purposes, Intel is providing a tool (Configuration Tool, or UI tool for DTT 9.x) that can show and modify DTT 9.x policy / participant settings.

2.2.1 Configuring Startup Scripts in DTT 9.x

DTT 9.x is comprised of several application components that are designed to work together to provide a flexible application framework for enabling certain application features. These components include:

1. Lower Framework (LF) – Device Drivers that run in the Kernel.
2. Upper Framework (UF) – User Mode application for abstracting OS and platform from Loadable Apps such as DTT and provides features such as a Web Socket server.
3. DTT Loadable App – Loadable Libraries that implement the DTT application and Policies.

In order for DTT to function, the DTT Loadable App must be started by the DTT Upper Framework. This is done automatically during system startup for a standard installation. By default, the following features are disabled when DTT is installed on a system:

Intel® DTT 9.0.11101.30293 Win 11 22H, 20H2, 20H1 Release Notes
November 2022



1. UI and Web Socket server used to monitor and configure DTT in a web browser.

OEMs can enable these features by following the instructions in this document.

2.2.2 Configuration Tool Quick Start Guide

To enable the UI and Web Socket Server, the quickest way to accomplish this is to run the “setup.exe” in the “Tool” folder to automatically install the Configuration Tool and reboot the system. Load the UI using one of the following methods with a HTML5 supported web browser. (Chrome or Internet Explorer 10 or higher)

- Open <http://localhost:8888> in your web browser
- A desktop shortcut is no longer created for DTT UI and instead the UI needs to be accessed by opening a browser and navigating to localhost:8888.

2.2.3 Troubleshooting

If you are unable to load the UI using <http://localhost:8888> after installing Configuration Tool or you are unable to view any data in the “Monitor Mode” of the UI after manually loading the index.html file, you may have to adjust some security settings in order to allow your browser to connect to “localhost”. The following are general troubleshooting steps:

- Verify Firewall and Security Settings:** Ensure that there is not a firewall (or another application) blocking access to port 8888 (or your specified port). Also, for Microsoft Internet Explorer, ensure that your security zone settings are not preventing an upgrade from the http to websocket protocol. To do this, go into Tools > Internet Options > Security > Local Internet > Sites > Advanced and add <http://localhost> to the list to force localhost into the Local security zone.
- Uninstall Intel® Dynamic Tuning Technology driver and tool.**
- Delete the folder**
“C:\Windows\system32\drivers\DriverData\Intel\DPTF”.
- Reinstall driver & tool and confirm the version is aligned.**
- Press “Ctrl+F5” to reload your browser.**

If Uninstall is not happening in presence of ICSS follow the given steps:

- Uninstall the existing DTT/DTT UI (and ipf If present)**
- Reboot**
- Go into Services and stop the Intel Context Service:**

	Intel(R) TATargetService	Gets the requested thermal data from the paltform and se
	IntelAudioService	
	IntelContextService	Intel(R) Context Sensing Service
	iphlpvc	Provides tunnel connectivity using IPv6 transition technol
	ipxlatCfgSvc	Configures and enables translation from v4 to v6 and vice

-
-
-
-
- Clean out all remaining drivers:**
 - See the powershell commands at the end of the email

Intel® DTT 9.0.11101.30293 Win 11 22H, 20H2, 20H1 Release Notes
November 2022



6. **Delete** the contents of these directories
 - a. C:\Windows\System32\Intel*



- b. C:\Windows\ServiceProfiles\LocalService\AppData\Local\Intel*
 - c. C:\Windows\System32\drivers\DriverData\Intel*
- 7. **Verify** no dtt drivers are left in devicemanager
- 8. **Reboot**
- 9. **Verify that the ICSS service** is no longer in services
- 10. **Install** IPF
- 11. **Install** DTT
- 12. **Install**
- 13. **Reboot**

Note: If this does not resolve the problem, check with your BIOS vendor to see if they have the same symptom or contact your Intel representative.

3 *Tools Support*

Table 1. Tool Support

Feature	Description
Configuration Tool	DTT Configuration Tool is provided to monitor and test DTT 9.x functionality for OEMs development / system validation use. After installing the DTT 9.x software stack, the user can run the tool and observe the policies, participants and temperature changes. Capture all the settings as one file.

4 *Feature Set – New to this release*

- IPF - Biometric Presence Sensor event stops providing data after S3 exit (with WAL enabled)

Table 2. Fixed Issues

Reference No:	Description	Root cause	Solution
22016016704	[LG][Gram 1xZ90R][RPL-P28] DTT(Dynamic Tuning Technology) driver can't switch action in APCT	This issue was caused by Intel® DTT removing its capability to update the OEM variable values in reaction to an OEM Variable Changed event.	A fix for this behavior was identified by removing this change.

6 *Issues – Known in this Release*

Table 3. Known Issues

Reference No:	Description	Impact	Workaround
N/A			

