




1.Prepare the bios files that need to be updated




2. Extract the zip file to the desktop, the path indicated by the arrow in the figure below, and check “show extracted files when complete”




3. Open the files




4. Select the address bar and copy the full name (ctrl+c <use keyboard>)




5.Right-click the Windows and select Windows Terminal (Admin) (1>2)




5.Click Yes




7.Type **CD** then paste the name of the file (ctrl+v) and press the Enter<use keyboard>.



8.Type **ls** and press the Enter.



8.Type **flash** and press <Tab> then Enter <use keyboard>.



Administrator: Windows PowerShell

Windows PowerShell
Copyright (C) Microsoft Corporation. All rights reserved.

Install the latest PowerShell for new features and improvements! <https://aka.ms/PSWindows>


PS C:\Users\Beelink> cd C:\Users\Beelink\Desktop\bios\bios\AfuWin64_FP55U302_3200U-20220324
PS C:\Users\Beelink\Desktop\bios\bios\AfuWin64_FP55U302_3200U-20220324> ls

Directory: C:\Users\Beelink\Desktop\bios\bios\AfuWin64_FP55U302_3200U-20220324

Mode	LastWriteTime	Length	Name
-a----	5/14/2021 11:02 AM	3579504	AFUWINGUIx64.EXE
-a----	5/24/2021 12:29 PM	1075824	AFUWINx64.EXE
-ar----	11/12/2020 3:20 PM	29056	amifldr64.sys
-ar----	11/12/2020 3:20 PM	35200	amigendr64.sys
-a----	3/24/2022 9:39 AM	44	Flash.bat
-a----	3/9/2022 11:22 AM	8388608	FP55U302.302

PS C:\Users\Beelink\Desktop\bios\bios\AfuWin64_FP55U302_3200U-20220324> flash

9.The system will enter the Bios update process



Administrator: Windows PowerShell

PS C:\Users\Beelink> cd C:\Users\Beelink\Desktop\bios\bios\AfuWin64_FP55U302_3200U-20220324
PS C:\Users\Beelink\Desktop\bios\bios\AfuWin64_FP55U302_3200U-20220324> ls

Directory: C:\Users\Beelink\Desktop\bios\bios\AfuWin64_FP55U302_3200U-20220324


Mode	LastWriteTime	Length	Name
-a----	5/14/2021 11:02 AM	3579504	AFUWINGUIx64.EXE
-a----	5/24/2021 12:29 PM	1075824	AFUWINx64.EXE
-ar----	11/12/2020 3:20 PM	29056	amifldr64.sys
-ar----	11/12/2020 3:20 PM	35200	amigendr64.sys
-a----	3/24/2022 9:39 AM	44	Flash.bat
-a----	3/9/2022 11:22 AM	8388608	FP55U302.302

PS C:\Users\Beelink\Desktop\bios\bios\AfuWin64_FP55U302_3200U-20220324> .\Flash.bat

C:\Users\Beelink\Desktop\bios\bios\AfuWin64_FP55U302_3200U-20220324>AFUWINx64.exe FP55U302.302 /p /b /n /x /k /r

```
-----+
|          AMI Firmware Update Utility v5.14.03.0039          |
| Copyright (c) 1985-2021, American Megatrends International LLC. |
| All rights reserved. Subject to AMI licensing agreement.      |
|-----+
Reading flash ..... Done
- FFS Checksums ..... Pass
- Check RomLayout ..... Pass
Erasing Main Block ..... 0x004B5000 (57%)
```

10. When Process completed appears, the program can be closed and the Bios update is complete.



```
Administrator: Windows PowerShell
-a----      3/24/2022   9:39 AM             44 Flash.bat
-a----      3/9/2022  11:22 AM        8388608 FP55U302.302

PS C:\Users\Beelink\Desktop\bios\bios\AfuWin64_FP55U302_3200U-20220324> .\Flash.bat

C:\Users\Beelink\Desktop\bios\bios\AfuWin64_FP55U302_3200U-20220324>AFUWINx64.exe FP55U302.302 /p /b /n /x /k /r
+-----+
|          AMI Firmware Update Utility v5.14.03.0039          |
| Copyright (c) 1985-2021, American Megatrends International LLC. |
| All rights reserved. Subject to AMI licensing agreement.      |
+-----+
Reading flash ..... Done
- FFS Checksums ..... Pass
- Check RomLayout ..... Pass
Erasing Main Block ..... Done
Updating Main Block ..... Done
Verifying Main Block ..... Done
Erasing Boot Block ..... Done
Updating Boot Block ..... Done
Verifying Boot Block ..... Done
Erasing NVRAM Block ..... Done
Updating NVRAM Block ..... Done
Verifying NVRAM Block ..... Done
Erasing NCB Block ..... Done
Updating NCB Block ..... Done
Verifying NCB Block ..... Done
Process completed.
PS C:\Users\Beelink\Desktop\bios\bios\AfuWin64_FP55U302_3200U-20220324> |
```