



Intel® Innovation Platform Framework (IPF)

Release Notes

October 2025

Revision IPF - 2.3.20200.4422

Microsoft Windows* 10/11 x64

Lunar Lake Platform, Panther Lake Platform

Intel Confidential



You may not use or facilitate the use of this document in connection with any infringement or other legal analysis. You may not use or facilitate the use of this document in connection with any infringement or other legal analysis concerning Intel products described herein. You agree to grant Intel a non-exclusive, royalty-free license to any patent claim thereafter drafted which includes subject matter disclosed herein.

No license (express or implied, by estoppel or otherwise) to any intellectual property rights is granted by this document.

All information provided here is subject to change without notice. Contact your Intel representative to obtain the latest Intel product specifications and roadmaps.

All product plans and roadmaps are subject to change without notice.

The products described may contain design defects or errors known as errata, which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Intel technologies' features and benefits depend on system configuration and may require enabled hardware, software or service activation. Performance varies depending on system configuration. No computer system can be absolutely secure. Check with your system manufacturer or retailer or learn more at [intel.com](https://www.intel.com).

Intel disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade.

© Intel Corporation. Intel, the Intel logo, and other Intel marks are trademarks of Intel Corporation or its subsidiaries.

*Other names and brands may be claimed as the property of others.

Copyright© 2025 Intel Corporation. All rights reserved.

Contents

1	Release Kit Summary	5
1.1	Release Kit Details.....	5
2	General Information	6
2.1	Important Notes.....	6
2.2	Intended Audience	6
2.3	Supported OS	6
2.4	Supported Collaterals	6
3	Installation and Configuration	7
3.1	Intel® IPF Software Stack	7
3.2	BIOS Setup Guide.....	7
3.3	Intel® IPF Software Stack Installation	7
4	Features Added	8
5	Features Changed or Modified	9
6	Features Deprecated/Removed.....	10
7	Issues Fixed.....	11
8	Security Issues Fixed	12
9	Known Issues.....	13
10	Kit Details.....	14



Revision History

Revision Number	Description	Revision Date
2.3.20200.4422	• Lunar Lake Consumer and Corporate Production Version MR6 Best Known Configuration (BKC) Software Package (Microsoft Windows 11 24H2– 64 bit) WW40-2025 • Panther Lake H12Xe(QS)/H404(EVQS) Consumer and Corporate Best Known Configuration (BKC) Software Package (Microsoft Windows 11 25H2/24H2–64 bit) WW40-2025 • Panther Lake H12Xe/H404/H484(ES2) Consumer and Corporate Best Known Configuration (BKC) Software Package (Microsoft Windows 11 25H2/24H2–64 bit) WW40-2025	October 2025

§§

1 *Release Kit Summary*

1.1 Release Kit Details

Kit Release	2.3.20200.4422
Target Platform	LNL, PTL
Contents	IPF Driver

§§

2 General Information

2.1 Important Notes

This is the information for validated platforms at ingredient level. For a complete list of supported hardware and operating systems, please refer to platform BKC or contact your Intel representative.

2.2 Intended Audience

The target audiences for the release notes are OEM/ODM platform thermal and hardware engineers, BIOS and system software engineers, component ingredient (Wi-Fi PSM, WWAN, NVMe Storage, Camera) procurement and design engineers.

2.3 Supported OS

This package supports the following Operating Systems:
Microsoft Windows* 11/10 x64 Edition 24H2,22H2,20H2, 20H1

2.4 Supported Collaterals

Please refer to the below mentioned supporting documents for the latest update on IPF.

- Intel® Innovation Platform Framework (IPF) Configuration Guide #[638930](#)
- Intel® Innovation Platform Framework Namespace User Guide #[732035](#)
- Intel® Innovation Platform Framework 1.x BIOS Specification #[640237](#)
- Intel® Innovation Platform Framework (Intel® IPF) Client Development #[685592](#)
- Intel® Innovation Platform Framework (Intel® IPF) Provider Development Guide #[685487](#)

§§

3 Installation and Configuration

3.1 Intel® IPF Software Stack

Component	Remarks
IPF Windows Setup	Single installer package. Required for all client apps like DTT, XTU and CST.
IPF Windows SDK	IPF EF SDK, for development using IPF EF.
IPF Core SDK	This is IPF Core SDK package only – no EF SDK. This is for development purposes, contains IPF core SDK primitive commands

3.2 BIOS Setup Guide

Please make sure IPF is enabled in your BIOS setup menu.

1. Reboot the system and enter the BIOS setup screen.
2. Go to "Intel Advanced Menu".
3. Enter "Power & Performance", then "CPU – Power Management Control" page.
 - a. Make sure "Intel(R) SpeedStep(tm)" is enabled.
 - b. Make sure "Turbo Mode" is enabled.
4. Enter "Thermal Configuration ", then "Intel(R) Innovation Platform Framework (IPF) Configuration" page.
 - a. Ensure "Intel® Innovation Platform Framework" show as "Enabled".
 - b. Mostly everything will be pre-configured, so change settings as desired.
5. Save and Exit.

3.3 Intel® IPF Software Stack Installation

1. Install the Chipset and Graphic driver.
2. Install IPF infs. Once Installation is complete it will show under "System Devices" of Device Manager. The recommended way for installation is using pnputil commands.


```
# pnputil.exe /add-driver ipf_acpi.inf /install
# pnputil.exe /add-driver ipf_cpu.inf /install
```
3. Reboot your system.
4. Make sure no device is yellow bang in Device Manager.

Note: Single installer: IPF no longer has a separate installer for IPF Core and EF components. All components will show as 2.x in Device Manager.

§§

4 *Features Added*

ID #	Description	As of Version
HSDDES# 22020885021	[PPM] IPF driver to be distributed as generic automatic updates on WU	2.3.20200.4422
HSDDES# 14024125207	Namespace Explorer Tool (MVP) Version 1.0	
IPFT-9627	Restrict loading of providers	
HSDDES# 22021143965	Battery Time-to-Empty Estimation Enhancement	
HSDDES# 15017606629	AEP PTL Context-Based-Charging	
HSDDES# 16027618132	[BIM] EF Support for Display (Internal) Brightness Change Event	
HSDDES# 22021290417	[DTT] Support for Hetero Parking on Graphics Workloads	
HSDDES# 14024032838	[IPF] Win11 25H2 OS & HLK Requirements	
HSDDES# 16027963719	[BIM] BIM Provider Request	
HSDDES# 22021369827	Expose IPF client SDK C Interface to C++ via dll	
HSDDES# 22020473650	[IPF] Restrict loading of providers in IPF Clients	

§§

5 **Features Changed or Modified**

ID #	Description	As of Version
IPFT-9671	Change the current implementation of having "Platform" in exclude section to throw an exception	2.3.20200.4422

§§

6 *Features Deprecated/Removed*

ID #	Description	As of Version
N/A	N/A	N/A

§§

7 Issues Fixed

ID #	Description	As of Version
HSDDES# 22021257473	[DELL][ARL-Hx] Better error handling, OPB policy occasionally shows "Initialization failure" after system reboot Fix Details - Update the implementation of GET_TPG_POWER_STATE_SUR to return GPU_OFF_STATE for everything other than the GPU_ON_STATE	2.3.20200.4422
HSDDES# 16027850750	[LNL] [PTL] Fan Primitives GFHT, GFLT, SFHT, and SFLT fail to return values	
HSDDES# 14024464722	Over-install of DTT SW INF fails due to existing provider with same name with State Separation syntax Fix Details – The Installation Configuration Error fixed with DTT version 9.0.11970.58463	
HSDDES# 16027738794	[PTL-P] [4-STAR] [DC3] [SNS] NamespaceMgr crash causes YB on Dynamic Tuning Technology Device Component during S4 Fix Details – On-demand loading of the core provider, as well as limit the scope of the core provider.	
HSDDES# 14025409027	[Lenovo IdeaPad] "DTT" yellow bang in DM after do S4/S5.(F/R:1/3 units,3/45cycles)	
HSDDES# 16028103519	SWLC change is only recognized by EPO when there is a WLC change Fix Details - The issue appears to be due to the fact that DTT is not enabling for the interrupt and it was expected that IPF will enable the interrupt when the associated event was registered for by DTT. Updating IPF to automatically enable the interrupt when the event is registered, resolves the problem	

§§

8 *Security Issues Fixed*

ID #	Description	As of Version
N/A	N/A	N/A

§§

9 *Known Issues*

ID#	Description	As of Version
N/A	N/A	N/A

§§

10 Kit Details

Additional Notes	As of Version
• Lunar Lake Consumer and Corporate Production Version MR6 Best Known Configuration (BKC) Software Package (Microsoft Windows 11 24H2– 64 bit) WW40-2025 • Panther Lake H12Xe(QS)/H404(EVQS) Consumer and Corporate Best Known Configuration (BKC) Software Package (Microsoft Windows 11 25H2/24H2–64 bit) WW40-2025 • Panther Lake H12Xe/H404/H484(ES2) Consumer and Corporate Best Known Configuration (BKC) Software Package (Microsoft Windows 11 25H2/24H2–64 bit) WW40-2025	2.3.20200.4422

§§