



1. Power on and press the keyboard delete, enter the BIOS, use the keyboard direction keys to find Chipset, select South cluster configuration



2. Select Power On in the Restore AC Power Loss option



3. Finally press F4 to save the settings.